

Im. 3. 29.

4 - JAN 1935

ent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"TAIFUN"

Report

Lon

No. 100828e

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

ature of Survey

When due

The Boiler Survey became due in 6,34.

In reply to enquiry the Owners now write to the effect that the above survey will be carried out by the Register of the U.S.S.R.

It is submitted the class of this ship be withdrawn (...)  
from the Register Book and three dots/inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class  
Insert ...

*[Handwritten signature]*

4/1/35

*[Handwritten signature]*

4.1.35

W1274-0075



© 2020

Lloyd's Register  
Foundation