

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME "SKAGERAK".

Rpt. Sld. No. 32895.

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*


The Committee recently agreed that provided Danish vessel, classed with the Germanischer Lloyd or Norske Veritas and taken over by the Ministry of Shipping were found or placed in satisfactory condition, for a period of six months, after general examination as set forth in Circular 1764, a record of Examined L.R. (with date) could be inserted in the Register Book.

The Sunderland Surveyors report the vessel generally examined in dry dock in accordance with the above; the bottom coated, some started shell rivets renewed, the deck doubled between No.1 hatch and the forecastle front; repairs to a Bridge deck plate, hatchways and minor repairs carried out.

The Surveyors recommend the notation Examined L.R.6,40 be assigned.

It is submitted ~~that~~ the notation as recommended be inserted in the Register Book.

Insert in S.R.L:- Exd L.R. 6,40- for 6 mos.



© 2019 *Handwritten signature*

7.6.40.
Lloyd's Register
Foundation
W128 0008