


s.s. "SAN FLORENTINO"

Proc rept. No. 94673

H.P. 1ST REDUCTION PINION found broken at Buenos Aires October 1936. Forward helix - teeth broken for a length of $3\frac{1}{2}$ " at its aft end. Aft helix damaged at aft end for about $\frac{3}{4}$ ".



← FORWARD END



© 2019
Lloyd's Register
Foundation

FRANK & SONS
SHIPPING, ENGINEERING
AND
COMMERCIAL PHOTOGRAPHERS,
SOUTH SHIELDS
© 2019
985

Lloyd's Register
Foundation

W128 -0110