

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Sh. Sc. M/V "SANSEI MARU"* Rpt. *Kob* No. *7410*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st Long
Transverse No. *8057*Depth "d" *21.5'*

Framing: Table No. _____

Description *Bulb Angle frames as approved.**2nd*
Longitudinal No. *24304*Proportions $\frac{\text{Length}}{\text{Depth}} =$ *13.92*~~Deck~~ Sheerstrake*as approved.**Revised Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A1 (Steel)

1 DK (Stl), 2nd DK (Stl) except in foremast & aftermost holds
Cell DB 228' 6 7/8 t, Yanks in way of tunnel 207 t, FPT 63 t,
APT 102 t.

FK, 5 BH, pt Cam, Lloyd's A & C P.

P 33' B 80' F 31'

W.L.
30.7.31

It is concluded the thicknesses of the sheerstrake and strake below at the ends of the vessel are ~~not~~ approved but the Surveyors should be requested to state if this is so. The Surveyors should ~~also~~ be requested to forward particulars of the tests of the steam wire & towline.

W1282-0126