

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

DISCLOSED
MAY 11 1929

No. in Reg. Book 85179 Survey held at on the Wood Iron Steel &c. SKALA

Date, First Survey Last Survey 19

By whom Harland & Wolff, Ltd. When 1920 MONTH 3

TONNAGE: GROSS 6600, UNDER DK. 6214, NET 4043

Built at Belfast Owners Sofusula Managers

Owners' Address (if not already recorded in Appendix to Register Book) Port belonging to Russian

RETAIN

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

W.B.=CellDBorDBa feet; uE&B feet; f feet

total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 97932 Port London

CHARACTER: for Special Survey	Date of last survey and of Periodical Surveys.	When Assigned how expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1			+LMC 9.32
Skeler dk			CL 9.32
wid freeboard 9.32			
S.S. Lon No 3-9.32			
Cargo battens not fitted in Skeler tween decks Society's Freeboard (if assigned) as painted on Ship and now verified			

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

M/M BOX
1283

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Paired or Repaired								
Paired or Repaired in place								

ESSENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (state if on feet)
King of Decks	State if Tanks now tested	Dbing. Plates under Sounding Pipes	When put on, Month Year
Wings	Bulkheads	Engine Room Skylights	Boats
ns & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Side Plating	Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained (State if wedges removed)
Stanchions	Rudder	Scuppers	Sails
Stanchions	Steering gear and its connections	Cargo Hatchways	Equipment letter
Stanchions	Windlass	Hatches	Anchors, No. of
Stanchions	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Chain Locker
Stanchions	Have Sluice Valves now been examined and found efficient?	Caulking ditto	Cables (State if now ranged)
Stanchions	Have Watertight Doors now been examined and found efficient?	Treenails ditto	length mean diam. (on board)
Stanchions	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stenson ditto	Rule length size
Stanchions		Transoms Pointers, & Crutches ditto	Hawser & Warps
Stanchions		Timbers of Frame at openings ditto	Standing and Running Rigging
Stanchions		Ditto Ditto at other places ditto	
Stanchions		Stringers, Clamps & Shelves ditto	
Stanchions		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptND24, &c."

Survey Fee (per Section 20)	£	Fees applied for	19
Special Damage or Repair Fee (if any) (per Sec. 20)	£	Received by me	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.

© 2021 Lloyd's Register Foundation

W1283-0136

