

REPORT of SURVEY for REPAIRS, &c.

DISCLOSED
BOX No. 126

Date of writing Report 19...
No. in Reg. Book. 61394
Survey held at on the ~~Wood, Iron or Steel~~ *Sc. ITACA III*
Date, First Survey Last Survey 19...
By whom *J. Pollock Sons & Co. Ltd*
When *1930*
Built at *Taversham*
Owners *Itaca Cia. Argentina, SA*
Managers *✓*
GROSS *107*
UNDER DK. *81*
NET *63*
Tonnage
Owners' Address
Port belonging to *Buenos Ayres.*

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER. ☒ for Special Survey. Date of last Survey and of Periodical Surveys.
Machinery and Boiler Surveys (including date of N.B., if any).

+ A -
Barge
11, 33
+ LMC 11, 30
+ LMC (M) 3, 33
OG 11, 33

Oil bry.
For River & Harbour Service
Carrying Petroleum in portable tanks

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
State if Tanks now tested	Bulb. Plates under Sounding Pipes	(State if on Felt)	When put on, Month Year
Bulkheads	Engine Room Skylights	Boats	
Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.	
Cement or Asphalt (State which.)	Oil Bunkers	Condition, how ascertained	
Rudder	Scuppers	(State if wedges removed)	
Steering gear and its connections	Cargo Hatchways	Sails	
Windlass	Hatches	Equipment letter	
Have pumps now been examined and found efficient?	Planking of Wood Vessels	Anchors, No. of	
Have Sluice Valves now been examined and found efficient?	Caulking ditto	Chain Locker	
Have Watertight Doors now been examined and found efficient?	Treenails ditto	Cables (State if now ranged)	
Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	length mean diamr. (on board)	
	Transoms Pointers, & Crutches ditto	Rule length size	
	Timbers of Frame at openings ditto	Hawser & Warps	
	Ditto Ditto at other places ditto	Standing and Running Rigging	
	Stringers, Clamps & Shells ditto		
	Salting ditto		
	(State if examined.)		

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1, 2, 4," or "to remain as classed and to have record of survey, 1, 2, 4, and the notations of ss. No. 1-24 and pEND24, &c."

Survey Fee (per Section 20) £
Special Damage or Repair Fee (if any) (per Sec. 20) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £
Fees applied for, 19...
Received by me, 19...
Surveyor to Lloyd's Register of Shipping.

Committee's Minute *FRI. 5 APR 1935*
Character Assigned *House own*
General Committee, *Thursday, 11th April, 1935.*
Classing Committee
Decision confirmed