

F.E.

Received by Chief Ship Surveyor

4/9/09

Received from Chief Ship Surveyor

VESSEL'S NAME

St S "Balniet II"

Report

Sub

No.

2869

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	✓	✓
Description of Framing:— Bulb angle, increased in size to (viz., ordinary, deep, zed, channel or bulb-angle). <i>compensate for large openings.</i>		

The machinery has been fitted at Belfast & the Surveyors report that the work required to be done to complete the hull has been carried out to their satisfaction.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed +100A1 (Stub) as recommended.

+100A1 (Stub)

1 St (Stt)

NB. Cmc DB 103 1796 F.P.T 556 APT 36

B.K 6" 3B.H. Cmc. Lloyd's at 60 2/101 B7 F30 Mchly Aff

TRD

FW

RBL  
4/9/09

© 2020

Lloyd's Register

W1285-0196