

to Chief Surveyors

Received from Chief Surveyors

26/3/35

SHIP'S NAME

"OAKGROVE"

Report

Mdb.

No.

15363

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

3rd No. 1 SURVEY PARTLY HELD.

1,34

due

When proposed to be completed

tion of Survey held, &c.,

The 3rd S.S. No.1, due 1,34, has been partly held by the examination of the bottom and rudder, chain locker, anchors and chain cables. A proposal to complete same within the year of grace was agreed to.

Repairs are required at the Special Survey.

The case is fully stated in endorsement dated 11.7.34.

The Middlesbrough Surveyors reported in January last the ship generally examined afloat and made recommendations for her to be chipped throughout for further examination.

The Owners' Representative stated at that time that he was not prepared to carry out the recommendations.

The ship subsequently sailed on a certificate issued by the British Corporation and the Surveyors presumed it was the Owners' intention to class her with that Society.

In reply to enquiry the Newcastle Surveyors have forwarded a letter from the Owners intimating that they have transferred the class of this ship to the British Corporation.

The year of grace expired 1,35.

It is submitted the class of this ship be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating

"OAKGROVE" (2)

withdrawal of class at the Owners' request.

Withdraw class
Insert ...

The Certificate of Classification to
be endorsed "*Cargo battens not
fitted*" and the same notation to be
printed in the Register Book.

[Handwritten signatures and date]
26.3.35.



© 2020

Lloyd's Register
Foundation

W1288-0379 2/2