

1 - JAN 1935

Steam Trawler "MARIA DOLORES"

The 2nd S.S.No.1 became due 3,32 and no part of this survey has been held.

The trawler has been laid up at Cadiz since about June 1931, and the usual undertaking has been furnished.

A general examination was held last month at Cadiz, and repairs and renewals were recommended to framing, bulkheads, casings, decks, hatchways, ventilators, rigging etc. Anchors and equipment require to be made good. The vessel requires to be examined in dry dock.

In reply to the classing letter of 21st ultimo the Barcelona Surveyor states the Owner has informed him that the question of dry docking is under consideration, and will probably be carried out at an early date. He desires to be informed of the Cadiz Surveyor's recommendations, and assumes that the Committee will not require the repairs to be carried out until the vessel is to be put into service.

In view of the proposal to dry dock the vessel at an early date, it is submitted action be deferred, and the question of whether repairs will require to be carried out while the vessel is laid up or when she is to be placed in commission, considered on receipt of the Surveyor's report. The Surveyor should be requested to state if in his opinion the vessel is efficient in the meantime.

The Barcelona Surveyor should be furnished with a copy of the recommendations for repairs in Cadiz report No. 1445, as desired.

*Ans. to C.B. 27/1/35  
S.D.L.*

*SPC*

*[Handwritten initials]*

1.1.35



© 2021

Lloyd's Register  
Foundation

W1296-0217