

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

ENCLOSURE.

26th February, 1923.

Dear Sirs,

With reference to the classification in this Society's Register Book of the steamer "PRESIDENT GOMEZ", I beg to acquaint you that when this vessel was built the stream and kedge anchors supplied were 4cwt. 3 qr. 10 lb and 2 cwt. 1 qr. 14 lb ex stock instead of 6 cwt and 3 cwt respectively as required by the Society's Rules. The Society's Surveyors at Rotterdam stated in November last that new stream and kedge anchors had been sent to the West Indies to be placed on board to replace the anchors referred to above. The Rotterdam Surveyors have now been informed by the Owners that the steamer is trading regularly between Curacao and Venezuela and that at one of these ports probably at Curacao the anchors can be verified.

As you may be aware the Society has no Surveyor stationed in the vicinity of Curacao and in the circumstances the Committee will be obliged if you will kindly appoint a competent and independent Surveyor to examine the marks on the new stream and kedge anchors on board the vessel and compare them with the certificates of test and furnish me with a report of this examination upon the enclosed form.

I may add that all fees and expenses in connexion with this matter must be paid by the Owners or their representatives and should accordingly be charged by you to them.

I am, Dear Sirs,
Yours faithfully,

Assistant to the Secretary.

Messrs. J. & D. Jesurun,
Lloyd's Agents,
Breedestraat No. 15,
Willemstad
(P.O.Box 116)
CURACAO, Dutch West Indies.

© 2020

Lloyd's Register
Foundation
W1298-0122