

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME TREDINNICK REPORT N. Yk No. 42227

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey CONDITION. ~~When due~~

Subject to repairs to indented plating etc (p.s.f)
and stem plating at the Owners' convenience, and to
permanent repairs to indented shell plates No.3 in
1st strake below sheer and No.2 in 2nd strake below
and framing in way (s.s.) and to port hawse pipe
at the first convenient opportunity.



Wals
14.5.42

© 2019

Lloyd's Register
Foundation

W130-0003