

REPORT of SURVEY for REPAIRS, &c.

Date of Survey Report 19... When Surveyed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

52044 on the Wood, Iron or Steel No. 134

TONNAGE:— Built at Renfrew By whom Dobnity & Co. When 1920 MONTH 7

GROSS 350 Owners via Rev. San Cristobal, Esq. Owners' Address

UNDER DEK. 350 Managers R.J.C. Dodds & Co. Port belonging to Tampico

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

B=Cell D B or D Ba feet; uE&B feet; f feet Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

al capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

st Report, No. 6168 Port L.A

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR