

# Undertaking Case

7 JUN 1935

Surveyors 4. 6. 35

Received from Chief Surveyors

NAME *S San Ugon*

Report *not*

No. 979

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Survey *Special Survey No 3* When due *5.33*

*1 General Examination*

The class is subject to a bower anchor being supplied at the first convenient opportunity.

The 1st S.S. No.3 became due 5,33.

The ship being laid up the Owners have furnished the usual undertaking.

In reply to enquiry Mr. French writes he has been informed by the Owners that this vessel is still laid up at Tampico and that she has a maintenance party on board continuously, who turn over main engines and auxiliaries once a week.

The year of grace expired 5,34.

It is submitted for consideration whether in view of the Special Survey being 2 years overdue a general examination should be asked for.

*Actual*

*BB*

*6.6.35*

*Si*



© 2021

Lloyd's Register  
Foundation

W1303-0041