

Chief Surveyors _____

Received from Chief Surveyors 26 NOV 1936

EL'S NAME "MONTEVIDEO" ex "AVESTRUZ" Report Lon No. 103269a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey _____ When due _____

The Boiler Survey became due on this vessel at the end of September last.

The Buenos Aires Surveyors now forward a letter from the new Owners of this vessel to the effect that they consider it unnecessary to continue her classification.


It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class. Insert ...

36.

PLATING to be DRILLED when vessel is ~~24~~ years old, or at next Special Survey thereafter.

25.11.36.



© 2021

W1305-0279

Lloyd's Register
Foundation