

1

5 FEB 1937

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME "STONEWELL" Report Lon No. 103299a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____



When due _____


~~The Boiler Survey became due on this vessel at the end of October, 1936.~~

A letter has now been received from the Cape Town Surveyor intimating that the Owners, (The South African Government) do not wish to retain the classification of this vessel.

It is submitted the vessel's class be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at the Owners' request.

Withdraw class. Insert ...

3.2.37.


© 2020

W1306-0002

Lloyd's Register
Foundation