

to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

"BUJUN MARU"

Report

Long

No. 103472

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

date of Survey _____

When due _____

*The 1st 55. No 2 became due 2-37.
See letter 9-12-37*

The Dairen Surveyor writes enclosing a letter from the Dairen Kisen Kaisha to the effect that they have decided to withdraw all their vessels from the Society's class.

It is accordingly submitted the class of this vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

[Handwritten signature]
29-12-37

The Certificate of Unsoundness is endorsed "Cargo battens not fitted" and the same notation to be entered in the Register Book



© 2021

Lloyd's Register Foundation

W1307-0272