

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME S.S. CANADIAN MARINERRpt. HpcNo. 1304

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry

Before this case receives the consideration of the Committee the Surveyor should be requested to state whether the Sizes of the poops and forecassle deck beams, the width of the Bridge deck Stringer plate and the after end thicknesses of the Strakes A, B & C are as stated in the Report as these Sizes differ from those shown on the approved plans and in Sister vessels. He should also be asked to state whether the Size and thickness of Centre Guide brackets at intermediate framing in the double bottom are as shown on the approved plans HPC and not as stated in the Report 6-1-21

Dr. 7.1.21See Letter 7/1/21Lloyd's Register
Foundation

W1309-0021