

1

8 DEC 1937

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"DENMARK MARK"

Report

Lon.

No. 103454

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The 2nd S.S.No.1 due 1,37 has been partly held.

The class is subject to bunker upper tween deck plating being permanently repaired.

In reply to enquiry the Kobe Surveyors now forward a translation of a letter received from the Owners intimating their decision for withdrawal of class.

It is submitted the class of the vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.



Lloyd's Register
Foundation

W1309-0264