

2m.1.15

1

Sent to Chief Surveyors 17.10.18

Received from Chief Surveyors

VESSEL'S NAME

Shells Andgroom

Report

SikNo. 17860**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

When due

The Downton pump & keel Anchor have been dispensed with at Owners request for the duration of the War. as approved.

3 100A 1 (Steel)


2 86 (Steel)

Cells D.B 34' 9616. A.P.T. 276

EK 6 BH Cen. Sigsaxer. P 34' B III. F 47

Carrying oil fuel F.P. above 150°F in double bottom.

The Certificate of Classification is to be issued in
"Cargo battens not fitted in twelve etc"
notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

W1212-0089