

Do. above Cr
Engine Roo
Gross Tonn
Less Crew Sp
Less above Cr
me Roo

MONTREAL"

TELEPHONE MAIN 7017

Lloyd's Register of Shipping

42 ST. SACRAMENT ST.

IS REGISTER,
LONDON.

MONTREAL, October 11th. 19 19.

27 OCT 1919

The Secretary,
London, England.

Dear Sir:-

S.

With regard to the S.S. "CANADIAN SEIGNEUR"

Montreal report 1718 in reply to your letter of the
23rd, September I have to state that the rivetting
of the bridge side plating is in accordance with the
rules.

The tween deck bulkhead stiffeners
are as stated in the remarks on the report,

Regarding the test of the first
bower anchor I took all these details from the
anchor certificates and while it is possible that the
test on the report may have been a clerical error on
my part, I have no means now of confirming this, but
will endeavor to examine this certificate if the vessel
returns to this port.

Yours very truly,

H. J. Alderson

© 2021

W1314-0064

Lloyd's Register
Foundation

Referred to the

Referred to the Chief Ship Surveyor.

[Signature]
OCT 27 1915

Also for Mr. S. A. Hill to note.



© 2021
Lloyd's Register
Foundation

Do. above Cr
Engine Ro
Gross Tonn
Less Other St
Tonn above Cr
Ro

Ship Surveyor
AME ST
ks of the Chic
e endorsement to co
o bring out clearly
presented in the end

erse No.

g: Table

udinal No

lge Deck
T Re

a view of

ader he app

repaired.

This ves

and the a

ssed

It is

are so required

approved 192