

Owners PETER BROWN  
Managers -Do.  
(Where necessary to be entered in Reg. Book)

Bridge Deck Stringer Plate, br'dth & thickness	40	10	40	10
" Angle on ditto	3½ x 3½	9	3½ x 3½	9
" Tie Plates				
" Deck, Material and thickness	IRON	6/6	IRON	6/6
Forecastle Deck Stringer Plate, b'dth & th'kns	30	6	30	6



Referred to the Chief Ship Surveyor  
and the Chief Engineer Surveyor,

*ad*

13 APR 1905

*C.H.f*  
13/4/05



© 2021

Lloyd's Register  
Foundation



TELEPHONE (NAT.)

Do. above Crown of  
Engine Room ...  
Gross Tonnage  
Loss Cured Space  
Loss Crown of

The  
size  
on  
tes  
is

PILARS, in 'twelve D  
Average space ...