

Power of Main Boilers 2  
of Donkey Boilers  
Pressure  
Main Boilers 180

Boilers, when made (Main) 1933  
Owners Ministry of Railways of the Republic of China  
Managers  
If Surveyed Afloat or in Dry Dock

(Donkey)  
Owners' Address  
(if not already recorded in Appendix to Register)  
Port Chinese Voya

Particulars of Classification  
Precisely as in Register

CHARACTER  
for Special Survey  
of last Survey and of  
Periodical Surveys.

COAL  
in Ferry  
Crew Service  
7.33

# Lloyd's Register of Shipping,

71, Fenchurch Street,

London, 16th March, 1936.

E.C.3.

To the Surveyors at SHANGHAI.

Name, Ferry "CHANGKIANG"

QUESTION.

ANSWER.

I shall be glad if you  
obtain from the Owners and let  
me know what arrangements they propose  
to carry out the Screwshaft  
which became due at the end of  
1.


*Coy*

Date:— 23<sup>rd</sup> April, 1936.

A letter has been  
addressed to the  
Department concerned at  
Shanghai, who will be  
informed as soon as we  
receive a reply.

*F.P.*

of funnel(s)  
ted under st  
ed under ste  
y. Boilers?  
ey Boiler?  
ey Boiler?  
fitted at th  
eing efficien  
the after c  
ciently lubri  
er bearing of  
power fitted



© 2021

Lloyd's Register  
Foundation

al Observations, Opinion, and Recommendation:—

Clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent  
any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9, 11, B.S.

ELMC 140 lb., F.D., &c.)  
CS 3, 34,