



# Lloyd's Register of Shipping,

7, T. do Caes do Tojo,

Lisbon, 9th April, 1932.



B. Scullard.

XXXXXX.

ENGINEER SURVEYOR.

S.S. "MOÇAMBIQUE"

Dear Sir,

Due to alterations in the Company's sailing list the above named vessel is now drydocked, Class Survey being advanced and repairs being carried out.

The anchors and cables have been ranged and the links, shackles and anchors carefully cleaned but it is impossible to make out any of the marks to compare with the certificates.

The certificates are complete and have been issued by the Society's proving houses those for the cable and one bower anchor being signed by the B.C. Surveyor and have the B.C. embossed stamp.

The vessel has three Bower Anchors and 270 fthms of 2 4/16" cable and I will be glad if you would advise me whether in this case the figure I could be inserted in the vessel's proposed class.

I am, Dear Sir,

Yours faithfully,

The Secretary,

LONDON

*[Handwritten signature]*  
Lloyd's Register  
Foundation

Reference to Mr. B. C. Scullard  
Reference to Mr. B. C. Scullard



Referred to the Chief Ship Surveyor.

Referred to Mr. S. A. Hill.

14 APR 1932

Yours faithfully,

I am, Dear Sir,

Yours faithfully,

whether in this case the light I could be inserted in the  
of S & J's cable and I will be glad if you would advise me

The vessel has three power anchors and also a  
Sulley and have the B.C. impressed stamp.

cable and one power anchor being signed by the B.C.  
issued by the Society's brooding houses for the

The certificates are complete and have been  
with the certificates.

It is impossible to make out any of the marks to compare  
the links, shackles and anchors carefully cleaned out

The anchors and cables have been ranged and  
Sulley being advanced and before being carried out.

That the above named vessel is now drydocked, Class

Due to alterations in the Company's sailing

Dear Sir,

S.S. "MOONBRIER"

LONDON

RECEIVED

1000

1000

1000