



Lloyd's Register of Shipping,

7, T. do Caes do Tojo,

Lisbon, 24th. August 1931.

LLOYD'S REGISTER
RECEIVED
-1 SEP 1931
LONDON

.Scullard.

ENGINEER SURVEYOR.

T.S.S."MOÇAMBIQUE".

Dear Sir,

I have to acknowledge your letter of the 21st. inst. with reference to the classing survey of the above named vessel and I note that you have received the duplicate set of plans from the shipbuilders.

I now enclose two sets of drillings taken so far. The after plating was not drilled as the vessel had to undock but is expected to redock shortly, when this will be done.

The waterline plating was drilled by the owners who are preparing a list of repairs to the vessel, which includes the renewal of several side and bow plates.

The thicknesses of the after plating will be sent as soon as this is drilled.

I am, Dear Sir,

Yours faithfully,

G. J. Scullard

The Secretary.

LONDON.



Lloyd's Register
Foundation

W1319-017

LONDON.

The Secretary.

Dear Sir,

P. 14

Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

Also for Mr. S. A. Hill to note.

1 SEP 1931

Yours faithfully,

I am, Dear Sir,

sent as soon as this is drilled.

The thicknesses of the after plating will be

includes the renewal of several side and bow plates.

who are preparing a list of repairs to the vessel, which

be done.

undock but is expected to redock shortly, when this will

tar. The after plating was not drilled as the vessel had to

I now enclose two sets of drillings taken so

set of plans from the shipbuilders.

named vessel and I note that you have received the duplicate
that with reference to the classing survey of the above

I have to acknowledge your letter of the 21st.

"S.S. WOODBROOK".

Lisbon, 21st August 1931.

Y. T. do Cae do Lolo,

inquired to register a vessel