

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

"FRANCE MARU"

Report

Lon.

No. 103561

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/32.*)

Nature of Survey

When due

No survey is due on this vessel.

The class is subject to the windlass cylinders being renewed at the Owners' convenience, to the windlass bed plate, E.W. repair 1,38 being specially examined and permanent repairs effected to engine room frames starboard side at the next drydocking.

The Kobe Surveyors now forward ^{copy of a} letter from the Owners intimating their desire to withdraw the vessel's classification.

It is submitted the class of this vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert (...)

30-5-35
[Signature]
[Signature]



© 2021

Lloyd's Register
Foundation

W1319-0202