

Y.S.S. Southland

Dunedin 17. 1550 a.

It is concluded the propeller shafts are fitted with  
continuous liners the full length of the stem tube  
within the vessel but Surveyor should confer

Y.R.

18. 2. 30

© 2021

Class. Lr to Ddu;

18/1/30

Lloyd's Register  
Foundation

In the circumstances, however, you should  
a careful examination of the cylinders, and if the same are