

10.30. The class is subject to the cone of the screw shaft being examined at the next dry docking.

432-0028

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "URANIA".

Rpt. Nwc.

No. 98248.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

Subject of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S-S~~ No.

This Survey, due 12,39 ~~partly~~ ^{now} held ~~now~~

~~completed~~, and the following repairs carried out (due to wear and tear):-

Some stays renewed and minor repairs.

Cone of the screw shaft examined and found satisfactory.

It is submitted the vessel is eligible to remain as classed, with notation of BS2,40; S1,40 as recommended.

Class without special condition.



© 2019

Lloyd's Register
Foundation

24.2.40.