

s/s "LORD BROUGHTON" ex "PATMOS"

Captain Thompson, of the Byron S.S. Co. Ltd, called and stated this vessel had lost her 3rd bower anchor and that a new anchor would be obtained and sent to Cardiff to be placed on board in about a week.

In answer to enquiry Captain Thompson was informed *by Mr. Bowling* the equipment letter of the vessel was "S".

Said.
24/1/21.



© 2019

Lloyd's Register
Foundation

W 132-0033