

1,920.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP'S NAME Steak 22 "LORD BROUGHTON" Rpt. Nwc No. 73892


The remarks of the Chief Ship Surveyor are desired on this case ^{for "Palmas"} for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor First Entry

The Surveyors should be requested to state the thicknesses of
poop & forecaskle side plating when forwarding their final report. They
should also state whether size given for stiffeners on longitudinal
hold bulkhead is correct as it is not in accordance with size on plan

Dr. 6.12.20.



4132-0041