

# Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 24th January, 1929.

Cert. No. 1759.

This is to Certify that at the request of Messrs. The Kobe Steel Works Ltd, Kobe. the Open Hearth Steel Forgings or Castings named below ~~was~~ were examined and tested at their works on December 8, 1928 to January 19, 1929 (6 visits) and found to be as far as could be ascertained, sound and free from defect.

Two (2) Intermediate shafts 9-1/2 inches dia.

Examined in finished condition.

~~Drop tests~~

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x 3/4" x 180°
D 2811 B 2	28.8	37	Good
E 991 A 2	30.8	33	"

These shafts are intended for Mitsui Bussan Kaisha  
Tanaka Ship No. 159-162 and ~~has~~ have been stamped as follows:-

Fee Yen 80.00

Expenses „ 3.00

D-2811-B2, E-991-A2  
LLOYD'S  
No. 1759  
19-1-29  
L.R.A.W.

*A. W. Latt*

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society"





Lloyd's Register of Shipping

(MEIKAI BUILDING)

35, AKASHI-MACHI,

Kobe, January, 1929.

Kobe,

Cert. No. 1759.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe.

the Open Hearth Steel Forgings or Castings named below were examined and tested at their works on December 8, 1928 to January 19, 1929 (6 visits)

and found to be as far as could be ascertained, sound and free from defect.

Two (2) Intermediate shafts 9-1/2 inches dia.

Examined in finished condition.

Test Mark	Tensile in Tons	Elongation in %	Bend
D 2811 B 2	28.8	37	Good
B 291 A 2	30.8	38	"

These shafts are intended for Mitsui Bussan Kaisha and have been stamped as follows:

D-2811-B2-B-291-A2  
LLOYD'S  
No. 1759  
10-1-29  
L.R.A.W.

Expenses 3.00  
Fee 80.00

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of the Surveyors, other Officers or Agents of the Society."

Lloyd's Register Foundation