

1

Chander

CABLEGRAMS, "SURVEYORS"

TELEPHONE 1952 HARRISON

No. 15

LLOYD'S REGISTER OF SHIPPING,  
MONADNOCK BLOCK,  
53 WEST JACKSON BOULEVARD,

have been  
in the case  
24/5/22.)

CHICAGO,

NOVEMBER 14th, 1917.

LLOYD'S REGISTER  
NEW YORK  
REC'D NOV 1 5 1917  
ANS'D \_\_\_\_\_

*ms*  
*8*

The Secretary,  
New York.

Dear Sir:-

With reference to your letter regarding thickness  
of of L Strake, S.S. "CHOCTAW", this should have been marked  
in the First Entry Report as on the midship section, that is  
22.8 lbs. from 1/2 length to 17.9 and 16.3 in Peaks.

The Writer regrets to find the slip also occurs  
in The First Entry Report No. 27, "WAR BANNER".

*quack*  
*with*  
*78*

Yours faithfully,

*J. Hand*

For the Surveyors.

*3.10.17*  
*W1321*  
*Wais*

ness



© 2021

Lloyd's Register  
W1321-0087  
Foundation

Fee Bulb, or Channel .....						
" Angles on upper edge .....						
" Spacing .....	24			24		
BEAMS, Bridge Deck, Angle, Bulb Angle, Plate, .....	6	3	13	6	3	13

" Angle on ditto.....  
" Tie Plates.....  
" Deck. Material and thickness *Steel*  
Forecastle Deck Stringer Plate, b'dth & th'k



not to Chief Surveyor

ESSEL'S NAN

(In case  
require  
so to  
ature of Survey

© 2021

Lloyd's Register  
Foundation



ertificate of  
to battens  
to be printed

S

6-12-17  
M

Spacing .....

Poop Deck, An  
For But, or

Angles on upper

Spacing .....

BEAMS, Bridge Deck, A  
For But, or

Angles on upper