

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

123 JUN 1938

VESSEL'S NAME "HARBIN MARU"

Report _____ Lon. _____ No. 103573a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____


When due _____

The Boiler Survey became due 1,38.

In reply to enquiry the Principal Surveyor for Japan forwards a copy of a letter received from the Owners in which they state that they wish to discontinue the vessel's class.

It is submitted the class of the vessel be withdrawn from the Society's Register Book and three dots(...) inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class
Insert ...



© 2021

Lloyd's Register
Foundation

W1322-0062