

5c.114.

F.E.

Received by Chief Ship Surveyor 17th April 1914

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "Doctor Lee"Rpt. Hull No. 24343

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 36.12Depth "d" 11.66Framing: Table No. 3 Page 9.Description Single Angle as approved.Longitudinal No. 4936Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.5}{}$

~~Deck~~ Sheerstrake .62 of an inch instead of .36 as required

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \therefore 100 A.1. (Steel). "Steam Trawler" as recommended.

\therefore 100 A.1. (Steel). "Steam Trawler"

1 ~~5~~

73 ft. 7 1/2' 40 ft. Beam Lloyd's ~~44~~ C.P. 9.44' F.20'

M

R.D.

20-4-14.



© 2021

Lloyd's Register
Foundation

W1325-0104