

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Fraternitas

Rpt. No.

10953

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey **COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 3**

This Survey, ~~was~~ partly held at ~~now~~

~~completed~~, and the following repairs carried out (due to *wear & tear*):-

Shafting lined up, pumps & condenser repaired:

*6 Press Boilers repaired
2 new " " and 4 second hand press
Boilers placed on board.*

*Propeller renewed & blades repaired
for damage - cause not stated.*

It is submitted the vessel is eligible to remain as classed, with notation of *Time 10.36. S. 6.36* as recommended.

P.B. 10.36

*Amend particulars of Press Boilers to
16 P.B. both
9 do 43th.*



© 2020

Lloyd's Register Foundation