

Hamburg Report Nr. 1989

10th August, 1929.

*Surveyed the Boiler and Machinery of the Steel Co. Sr. "SIR JAMES CLARK ROSS" 8224/4882 tons of Sandefjord afloat and in drydock at Kiel for annual boiler survey, alterations and repairs xxxx*

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the records of "B.S.-8,29" and "Fitted for Oil Fuel 8,29 F.P.above 150°F." ~~XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX~~

*be made in the Register Book in the case of this vessel.*

Friedrich Hill  
Engineer Surbeyor to Lloyd's

Engineer Surveyor to Lloyd's Register.

“While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.”