

1.

Urgent

SIR 17/11/05 CLARK 1905

COPY.

Fraternitas

9th December 1905.

Sir,

I am in receipt of your letter of yesterday respecting the steamer "MAHRONDA" and in reply thereto, I have to inform you that the cement was not laid on the inner surface of the bottom plating inside the double bottom of this vessel when she was built, except over the sunken strakes and in the boiler space as specified by the Owners, and the vessel was classed by the Committee +100A1, subject to each compartment of the double bottom being examined at least each year.

I am, Sir,

Your obedient Servant,

A. Hill
Secretary

R. Williamson Esq.,
Liverpool.



© 2020

Lloyd's Register
Foundation

W133-0250

W133-0251