

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19

35287 on the Wood, Iron or Steel
TONNAGE:-
GROSS 3080
UNDER DK. 2843
NET 1807
Built at Glasgow
By whom Hsu Yi Tien
Owners' Address
Managers
When 1920 - 1
Port belonging to Chefoo Jap.

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B. All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5549 Port Den

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	(State if on Felt).
Coamings	Bulkheads	Engine Room Skylights	When put on, Month Year
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Boats
Outside Plating	Cement or Asphalt	Oil Bunkers	Masts, Yards, &c.
" " in way of sidelights	(State which.)	Scuppers	Condition, how ascertained
Breasthooks	Rudder	Cargo Hatchways	(State if wedges removed)
Transoms	Steering gear and its connections	Hatches	Sails
Frames	Windlass	Planking of Wood Vessels	Equipment letter
Reverse Frames	Have pumps now been examined and found efficient?	Caulking ditto	Anchors, No. of
Longitudinals	Have Sluice Valves now been examined and found efficient?	Treenails ditto	Chain Locker
Transverses	Have Watertight Doors now been examined and found efficient?	Breasthooks & Stemson ditto	Cables (State if now ranged)
Floors	Have Ventilators and their Coamings been examined and found efficient?	Transoms Pointers, & Crutches ditto	" length mean diamr.
Keelsons		Timbers of Frame at openings ditto	(on board)
Stringers		Ditto Ditto at other places ditto	" Rule length size
Inner Bottom Plating		Stringers, Clamps & Shells ditto	Hawser & Warps
		Salting ditto	Standing and Running Rigging
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptnd24, &c."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19...
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19...

Committee's Minute

Character Assigned

FRI. 24 JUN 1938

FRI 1 JUL 1938

FRI 26 AUG 1938

Surveyor to Lloyd's Register of Shipping.

Is Certificate required? If so, to be sent to

General Committee
Thursday, 1st September, 1938
Classing Committee's decision
conformed
L.B.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form :—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT.		WEIGHT		TEST	WEIGHT REQUIRED	Description of Anchor.	Makers.	Where and when tested and Superintendent.
		EX. STOCK.	Cwts. qrs. lbs.	OF STOCK.	Tons qrs. lbs.	PER CERTIFICATE.	BY RULE.			
	1st Bower ...									
	2nd "									
	3rd "									
	Collective Weight.									
	Stream									
	Kedge.....									

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.	WEIGHT OF CHAIN CABLE.		Length and size per Rule.	Description.	Makers of Cables.	When and where tested and Superintendent.
	Length.	Diam.		Supplied.	Per Rule.				
	Fathoms.	Ins.	Tons.	Tons qrs. lbs.	Cwts. qrs. lbs.	Fathoms.			

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2021
Lloyd's Register
Foundation