

W1330-0162

Wam Shun

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "ALGERIER"Report GLs.No. 39589

## For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The Downston Pump has been dispensed with for the present, but it is concluded the Owners are agreeable to fit same when requested.

\* 100 A.1. (steel)

2 Dks (steel).

Cell DB 278', 735t.

FPT 106t.

APT 42t.


FK 6BH. Com.

Lloyds A9CP.

P33', B 100', F28'.

Forging reports not yet to hand

© 2021

Lloyd's Register  
Foundation

6.2.20.