

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME STEEL S.S. "WAR GAEKWAR" Report Greenock No. 17540

For the CHIEF SHIP SURVEYOR ~~STEEL S.S. "WAR GAEKWAR"~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

ture of Survey

When due

The Downton Pump has been dispensed with for the Present.

- ❖ 100 A.1. (steel) Carrying oil fuel in bulk F.P. above 150°F.
- 1 Dk. (steel) 2 trs beams & Webframes. Longitudinal Framing.
- Cell DB uB+B 72' 250t. & 50' 65t. F.P. 95t. A.P. 75t.
- FK. 11BH. pt.cem. Lloyds A+C.P. P50', B121', F39'
- Middle line Bulkhead not oil tight.

© 2021

Lloyd's Register Foundation

The Surveyors should be requested to forward the usual Ship Findings & Continuity report

9.10.19

W 1333-0089