

s/s "Tsurishima Maru."

It is submitted the Yokohama Surveyors should be informed it is concluded that spare feed & bilge pump valves have been placed on board, but as these are not reported they should state whether this is so.

HERD.
17/9/19.

Lloyd's Register
Foundation

W1335-0071