



Lloyd's Register of Shipping,

Ramsden Square,

Barrow-in-Furness,

31st. August. 1921.

LLOYD'S REGISTER
LONDON.

REC. 1 SEP 1921
ANSD

The Secretary,

L O N D O N.

Sir,

With reference to your letter of the 30th inst, regarding the S.S. "Canadian Importer", Vancouver Rpt No 782, I beg to state in reply that the stern frame for this vessel was examined for workmanship when being assembled in the machine shop and on completion was tested for alignment, and found in order..

I cannot understand how this Scarph could open up under ordinary conditions of service, as the workmanship in my opinion was satisfactory, and I am inclined to think that the damage sustained must have been caused by external factors of which no particulars are available.

I am Sir,

Your obedient Servant.

John. Whitehead

© 2021

Lloyd's Register
Foundation

W1335-0115

P.S. Chief Engr. Report. enclosed

For the Chief Ship Surgeon

A.S.

1/9/21

Surgeon St John NB.

For our Magazine
to note

dated. insurance, funding
to summing, letter of 50d. ult.

to
2/19/21.

PH



© 2021

Lloyd's Register
Foundation