

No. of excess of Hatchways *22* By whom built *N.V. Be*  
Do. above Crown of *England* stern post *155.00* Owners *Trust C*  
Longitudinal Number *5960.1*

Time of Receipt *11.38*

# TELEGRAM.

LOYDS REGISTER

LONDON

21 FEB 1914

REC'D  
NSD



## POST OFFICE TELEGRAPHS.

If the accuracy of this Telegram be doubted, a part, or the whole, can be repeated under special conditions, particulars of which can be obtained on application at the office from which it was delivered.

This form must accompany any inquiry made respecting this Telegram.

Office Stamp.



Office of Origin and Service Instructions.

Charges }  
to pay }

+ ROTTERDAM 0627 16 21 10.55 M =

Received here at

*11.22*

= COMMITTEE LONDON = WAITING TONNAGE FEES SAINT

MICHEL REPORT 8244 BUILDER GARANTEES

PAYMENT AT ONCE = LLOYDS REGISTER .+



© 2021

W1336-0138 0140

Lloyd's Register  
Foundation

W1336-0151

Angles on upper edge *under top and bridge*  
Spacing *Combined*

Deck. Material & thickness  
Peop Deck Stringer Plate breadth & thickness



FEB 22 1913

CSK

FEB 21 1913

TELEGRAM

© 2021



Lloyd's Register  
Foundation

Am

Prefix

Words

Office of Origin

Notice.—The following  
pursuant to the Telegram

The Sender's Name  
and Address, or either  
of them, if to be telegraphed,  
must be written at the  
beginning of the text of the Telegram

I request that the following  
be printed on the Telegram  
Signature and Address

\* This space

JO

BEAMS, Third and Fourth Deck  
Spacing .....  
Angles on upper edge .....

Dec. of access of Hachways in  
Do. above Crown of  
Endways