

Chief Surveyors 27/7/10

Received from Chief Surveyors

NAME Stl. S. S. "Den of Glamis" Report Gls. No. 29131.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Surrey 1st Entry. When due

✦ 100 Al ("Steel")

2 Dks (stl.)

WB = all DB a 134' 0" E + B. 43' f 180' = 1070'. D.T. a 33' 880'. A.P.T. 60'.

FK. GBH. Lem. Lloyds A+C.P. P. 38' B. 119' F50'

Ed. L.

It is concluded the beams of the 2nd deck are 11" x 3½" as marked in pencil on the approved plan of midship section & not 11" x 3" as given on the Report but the Surveyors should state if this is so.

" " " breadth, & thickness
 " No. of Side Stringers " "
 B-FRAMES, In E. & B. Space, No. & spacing

BULKHEADS.	Number.		Thickness.	STIFFENER	
	Vessel.	Per		Horizontal.	Vertical.
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					
47					
48					
49					
50					
51					
52					
53					
54					
55					
56					
57					
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					
70					
71					
72					
73					
74					
75					
76					
77					
78					
79					
80					
81					
82					
83					
84					
85					
86					
87					
88					
89					
90					
91					
92					
93					
94					
95					
96					
97					
98					
99					
100					