

1734  
 UNDER DE. 1168  
 Managers  
 Port belonging to  
 Surveyed Afloat or in Dry Dock? Name of Dock  
 Cell DBor DBa feet; uE&B feet; f feet  
 total capacity tons. FPT tons; APT tons; MT feet tons.  
 Only alterations in the existing records of tanks should be inserted.  
 N.B.—All alterations in the existing records should be underlined.  
 Last Report, No. 10709 Port Kobe  
 Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules and Items reg  
 complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the  
 tent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which  
 could be separated from Repairs due to other causes; and besides being detailed in the body of the re

# Lloyd's Register of

The Boiler and Screwshaft Surveys became due in June last.

In reply to enquiry Mr. H. Jasper Cox, the Society's Principal Surveyor for the Far East, now states that he has been informed by the Owners that the above vessel has been requisitioned by the Government and they no longer desire to maintain her class in the Register Book.

In the circumstances the Classing Committee, who had the case before them on Friday, the 9th instant, decided to give instructions for the vessel's character to be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof indicating withdrawal of class at Owners' request.

15th February, 1940.



© 2021

Lloyd's Register  
 Foundation

Surveyor to Lloyd's R

Second Surveyor's Fee (if any)

Committee's Minute

General Committee