



# Lloyd's Register of Shipping.

TEMPORARY ADDRESS

ward (if assigned) as }  
up and now verified } ..... ft.

1m.10.30.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME "ROKOSAN MARU".

Report

Lon. No. 108283a

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

The Boiler and Screwshaft Surveys became due 6,39.


In reply to enquiry Mr. Cox writes he has been informed by the Owners that the vessel is under Government requisition and they do not desire to continue her classification.

It is submitted the class of the vessel be withdrawn from the Register Book and Three Dots(...)inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class

Insert ...

*W.A. Acl*  
8.2.40.2021



W1348-0053

Lloyd's Register  
Foundation

W1348-0054

Book consequent u  
and to have record