

3m, 8, 21.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S.S. "DAVANGER"*

Report

Jul

No. *17955*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

❖ 100. A-1. (Steel) "Carrying petroleum in bulk"
2 Dks (Steel) & Webframes. Longitudinal framing
Cell WB & E. B 84' 153t, ITf 38 552t, APT 56t.
FK, 15 BH (9 to upper dk, 6 to 2nd dk) pt Cms, Plyas A & CP.
P101' B27' F43' Mchly Off.



© 2021

Lloyd's Register
Foundation

W1351-0098

Remainder in Hold

Tie Plates, outside Hatchways