

in damages cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard
painted on Ship

"ROBERT BORNHOFEN"

On Tuesday, 4th June, 1940, a list of German Owned vessels, classed with Lloyd's Register, was submitted to the Classing Committee, who gave instructions that the class of each vessel should be omitted from the Reprint of the Register Book for 1940-41.

(Original papers with "H" Department).

The list referred to above included the name of the S.S. "ROBERT BORNHOFEN".

*D.Pro. 217
Section 3*

For Mr. Boxall)
H Dept.)
Mr. Munro) tp note.



© 2021

Lloyd's Register
Foundation

W1353-0083

Reverse frames.....	client /	greenais	ditto.....
Longitudinals.....	Have Sluice Valves now been examined and found	Breasthooks & Stemson	ditto.....