

to what parts of the Boilers ...
to what special means, in the absence of internal examination, were adopted by the
Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

20, 11, 38.

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "PENTLAND FIRTH".

Rpt. Hul. No. 49910.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 1

This Survey, due 11, 38 ~~partly~~ now held
~~completed, and the following repairs carried out (due to~~

Screw shaft examined; stern-bush rewooded; minor wear and tear repairs effected.

It is submitted the vessel is eligible to remain as classed, with notation of ~~ELMC~~ 4, 39, S 4, 39 as recommended.



© 2021

16.5.39.
Lloyd's Register
Foundation

W1353-0162