

6. of Feed pumps 2 ✓ Diameter of ditto 3 1/2" Stroke 2 1/2" Can one be overhauled while the other is at work Yes ✓

Time of Receipt

# TELEGRAM.

9310) Wt. 29512/1171 16,000,000 4/23 Harrow G.149

1254

B or C. RECEIVED - 11/10/18 M.	Charges to pay s. d.	<b>POST OFFICE</b>  <b>TELEGRAPHS.</b> If the receiver of an Inland Telegram doubts its accuracy he may have it repeated on payment of half the amount originally paid for its transmission, and if it be found that there was any inaccuracy the amount paid for repetition will be refunded. Special conditions are applicable to the repetition of Foreign Telegrams. <b>THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM.</b>	No. of Telegram SENT	Office Stamp. FEB 10 1892 5 00T23
			At.....M.	To.....

x Time handed in 1.22 M.	Office of Origin and Service Instructions Newport Mon 21	Words 5
-----------------------------	---	------------

Committee Ten Ldn  
 Cynthiaiana four suction  
 fitted in engine room stop  
 back point of oil not less  
 than 150 degrees. Surveyor



© 2020

Lloyd's Register Foundation

W1358-0023

of Test

Is a Safety Valve fitted to each Section of the Superheater which can be shut off from the Boiler

375 Gd No.

Referred to the Chief Engineer Surveyor.

7th

CMS



© 2020

Lloyd's Register  
Foundation