

Ship Surveyor 19. 6. 17

Received from Chief Ship Surveyor

HALF ME Single Sc.Sr. "SHINSEI MARU". Rpt. Yka. No. 2251

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

It is submitted the Surveyor be requested by cable to state whether the brackets to intermediate floors at margin plate as shown on the approved sketch of midship section, also whether hawsers and warps have been supplied as per Rule.

He should also state the thickness of the butt straps bridge sheerstrake; and whether the vessel has been built in accordance with approved plans, copies of which should be forwarded.

*M.*  
19. 6. 17



Table with columns for measurements and ship details. Visible entries include: 4x4x, 5x5, (40, 6x6, 7x7, wide, Inches in Ship, 56, 56, 5x, .4, .4, 48x, 3 1/2, .3, .2, no, fu, fu, 33

rate traffic.  
names or w  
to the Sende  
Telegram ren  
rolled, then  
mission or de  
rolled by the  
on or non-de  
fault on the  
ond the am  
error, or om  
ision of the T  
controlled by t  
ure system or  
ed by them.  
the addre  
ling to the  
duced rate  
the Eur  
gime (incl  
ountries i  
cept by s  
grams are  
is not less  
to irreg  
serve the  
which in  
conditions.  
telegram be  
or L.C.D.  
s treated i  
ons.  
telegram  
grams and  
their destin  
banding i  
at the full  
es are deli  
duced rates  
ept that rel  
s special ser  
um (paid se  
e.), are the  
e correspon  
at the red  
elegrams are  
at reduced  
onal Regula  
ions.  
ons; further

cond Deck, Single Angle, Bun  
Angle, Plate, Tee Bulb, or Channel  
" " Deck. Material & thickness  
" " Deck Stringer Plate length & thickness